## WATER TEST REAGENT

## For Laboratory Use Only

SMALL VOLUMES USED CONTAINER SIZE RANGE

## MATERIAL SAFETY DATA SHEET

2 OUNCE - 1 GALLON MAXIMUM

S DAMPE . T BUTTOM MAYIMAM	·			
Section 1 - PRODUCT IDENTIFICATION				
DEARBORN CHEMICAL CO., Subsidiary,	Co.	EMERGENCY PHONE NO. 312/438-8241		
300 Genesee St., Lake Zurich, IL 6	0047			
CHEMICAL NAME AND SYNONYMS Activated powdered charcoal			TRADE NAME OR CODE IDENT.  Code 511	
Section 2 - INGREDIENTS	CAS No.	%	EXPOSURE CRITERIA	

## NON - HAZARDOUS MATERIAL

The product identified in this Data Sheet is NOT a hazardous material within the meaning of Title 29, Code of Federal Regulations 1915, 1916, 1917.

<b></b>					•	
Section 3 — PHYSICAL DATA		·	· · · · · · · · · · · · · · · · · · ·			
BOILING POINT, 760mm Hg		N/A MEI		NG POINT	N/A	
SPECIFIC GRAVITY (H <sub>2</sub> 0 = 1)		N/K	VAPOR PRESSURE			N/K
JAPOR DENSITY (AIR = 1)		N/K	SOLUE	ILITY IN H <sub>2</sub> O, % BY	WT,	n/k
% VOLATILES BY VOLUME		N/K		PRATION RATE,	= 1	N/K
APPEARANCE AND ODOR Black	powder	· · · · · · · · · · · · · · · · · · ·	рН	·		N/K
Section 4 – FIRE AND EXPLOSE	SION HAZ	ZARD DAT	ГА			
FLASH POINT (and Method Used) None		FLAMMABI LOV	LE LIMITS in VER	AIR,% by VOLUME UPPER	AUTO IGNITION N/A	N TEMPERATURE
EXTINGUISHING MEDIA Water Fog	0	Foam	□ CO <sub>2</sub>	☐ Dry Chemical	☐ Othe	r .
SPECIAL FIRE FIGHTING PROCEDUR  UNUSUAL FIRE AND EXPLOSION HA	N:	one				
		None		·	·	
• Section 5 - REACTIVITY DAT	A	•	<u></u>			
STABILITY (Normal Conditions)  Stable Unstable	CONDITIO	ONS TO AV	OID	None		
INCOMPATIBILITY (Materials to Avoid)				None	•	
'AZARDOUS DECOMPOSITION PROD	UCTS		None		· · · · · · · · · · · · · · · · · · ·	-
			•			•
HAZARDOUS POLYMERIZATION  「May Occur 図 Will Not Occur	CONDIT	IONS TO AV	/OID	None :		
					(ove	r)

MATERIAL SAFETY DATA S		• • •	
<ul> <li>Section 6 HEALTH HAZA</li> <li>EXPOSURE LIMIT</li> </ul>	ARD INFORMATION		
	mppcf - avoid nuis	ance dust.	
EFFECTS OF OVEREXPOSURE			
	cted in small amount	s as used for testing.	
INGESTION Not considere	ed toxic, but avoid	internal use.	· · · · · · · · · · · · · · · · · · ·
			•
SKIN OR EYE CONTACT Brawin	sh off skin and was th clear water.	n with soap and water. Flush eyes	
EMERGENCY AND FIRST AID PRO	OCEDURES		·
	Non	<b>a</b>	
		<b>~</b>	•
			•
A C. C. T. CREOLAL BROT	FOTION INFORMATIO		
<ul> <li>Section 7 - SPECIAL PROT VENTILATION REQUIREMENTS</li> </ul>	ECTION INFORMATION	V	
/ / / / / / / / / / / / / / / / / / /		Mechanical	
RESPIRATORY PROTECTION (Spe	cify Type)		
		None	·
EYE PROTECTION		GLOVES (Specify Type)	
None		None	
OTHER PROTECTIVE CLOTHING	AND EQUIPMENT (Specify )	ype)	
	·	None	
Section 8 - SPILL OR LEAF	CPROCEDURES		
STEPS TO BE TAKEN IF MATERIA		D	***************************************
Sweep up material and	place in waste cont	ainer.	
WASTE DISPOSAL METHOD			<del></del>
Dispose by placing ca	pped bottle in waste	container for landfill trash dis	posal.
<ul> <li>Section 9 — SPECIAL PRECA</li> </ul>	· · · · · · · · · · · · · · · · · · ·		
PRECAUTIONS TO BE TAKEN IN H Protect container fro		Keep closed when not in use.	
OTHER PRECAUTIONS			
	ls, NOI, Water Testi	ng Reagents - NOT RESTRICTED	
IATA		Prepared By W. M. Morris	
		Date: 8/79	